APPLICATION



FRP WINS AGAINST HIGH **COMMODITY PRICES**

In 2011, a national retailer became a theft target due to the high commodity scrap prices for steel. The issue was theft of steel grating from the drainage systems in the loading zones of the large retail chain. The long fabrication times and high steel prices led to expensive replacement costs and aesthetic deterioration due to water runoff and the varying age of the steel grating. Wood was used as a temporary measure; however the nature of wood eventually led to rot. The retailer's goal was to use as much non-metallic structural products as possible in the drainage system to prevent water and trash buildup while thwarting thieves.

Strongwell's DURAGRID® 1.5" HD-5000 pultruded grating was specified in eight installations to ensure prolonged years of maintenance-free service. FRP's high strength, light weight and easy-to-install characteristics ensured the retailer had operational access to its loading docks during installation with minimal downtime.

As steel prices remain high, the heavy duty HD grating will remain a permanent, corrosion-free fixture in this retailer's loading zone while ensuring full drainage capabilities for years to come.

TECHNICAL DATA

Product: Heavy Duty Drainage Covers

Process: Pultrusion

Materials: DURAGRID® fiberglass reinforced grating

Sizes: DURAGRID® HD-5000 1.5" grating

For: McNichols Company

User: A global discount retail chain



STRONGWELL

Chatfield Location 1610 highway 52 South Chatfield, MN 55923-9799 USA (507) 867-3479, FAX (507) 867-4031 www.strongwell.com

APPLICATION PROFILE 839